


## DIAGRAM SHOWING CORRECT CAMERA POSITIONING

CAMERA TO ANGLE DOWN OVER  
PATIENT OFF CENTRE AT AN  
OBLIQUE ANGLE TO MAXIMISE  
OBSERVATION EFFICIENCY - NOT  
HORIZONTALLY THROUGH THE  
CENTRE OF THE SCANNER BORE

IF A WARDRAY PREMISE  
MR6000/fMRI MONITOR IS FITTED  
TO THE WALL THE CAMERA  
SHOULD BE FITTED TO SUIT



**CORRECT**  
**WRONG!**

**WARDRAY  
PREMISE**  
Wardray Premise Limited  
Unit 2 Muggins Chambers  
26-28 Muggins Road  
Sutton-in-Ashfield  
Nottinghamshire  
NG17 4LE  
UK  
Telephone: +44(0) 20 8398 9911

**Project**  
**FITTING DETAILS**  
**MRI CCTV OBSERVATION CAMERA**

**Title**  
**CORRECT CAMERA POSITION**

Scale NTS@A4	Date 25/3/2010	Drawn by M CHUDLEY
Job Number 1641	Drawing Number 1641	Revision